



**SAMSON**

ORIGINAL NAIL FOUND 1.0m TO BOUNDARY

ORIGINAL NAIL FOUND 1.0m TO BOUNDARY

**ROAD**

ORIGINAL PEG DISTURBED (RENEWED)

97°15'20"  
9.14

SLAB 0.90m TO BOUNDARY

SPIKE ON BOUNDARY

SPIKE 0.5m TO BOUNDARY

LOT 100  
(D113077)

NEW SLAB (DWELLING UNDER CONSTRUCTION)  
7'16"20"  
43.76

LOT 101  
400m<sup>2</sup>

LOT 44  
(D3994)

SPIKE 0.5m TO BOUNDARY

GUTTER 0.09

SLAB 0.90m TO BOUNDARY

SPIKE ON BOUNDARY

SPIKE 0.5m TO BOUNDARY

GUTTER 0.08

NOT FENCED

THE FENCE ON THE EASTERN BOUNDARY WAS MEASURED TO THE WESTERN FACE

ORIGINAL SPIKE FOUND 1.0m TO CORNER

STAR DROPPER 0.5m X 0.5m TO BOUNDARY CORNER

277°15'20"  
9.14

GIF ON BOUNDARY

CBOND 0.05

LOT 32  
(D3573)

LOT 31  
(D3573)

### LEGEND

F=FENCE (F0.15 = FENCE TO BOUNDARY 0.15m)  
CBOND = COLOURBOND FENCE  
GIF = GALVANISED IRON FENCE

28/02/2020

SIMON KLITSCHER  
Licensed Surveyor



## WOODVILLE SOUTH IDENTIFICATION SURVEY

|             |       |       |           |              |               |
|-------------|-------|-------|-----------|--------------|---------------|
| SURVEYED BY | SK    | DATE  | 27/2/2020 | SCALE        | 1:150(A3)     |
| DRAWN BY    | SK    | DATE  | 28/2/2020 | FILE REF     | 12.20-PEG.DWG |
| CHECKED     | SK    | DATE  | 28/2/2020 | CO-ORDINATES | MGA2020       |
| JOB NUMBER  | 12.20 | DATUM | N/A       | HEIGHT DATUM | N/A           |

**IMPORTANT NOTE**  
This is not a certified survey for the purposes of the regulations under the Surveyors Act 1993. This plan will not be examined for boundary definition or otherwise by the Registrar-Generals Office. Any differences so caused by subsequent surveys to the boundary definition shown on this plan are beyond the control of Reliable Surveys Pty Ltd who can accept no responsibility for such differences.

**RELIABLE SURVEYS PTY LTD**  
 ABN 17 637 659 498  
 PO BOX 226, BROOKLYN PARK SA 5032  
 MOB: 0416 366 387  
 EMAIL: simon@reliablesurveys.com.au

SHEET NUMBER 1 OF 1 REVISION 0