



TBM#5 (NAIL)
E: 272880.146
N: 6124067.442
RL: 4.738

TBM#2 (NAIL)
E: 272881.183
N: 6124054.159
RL: 4.826

PSM 6627/8674
E: 272884.859
N: 6124005.442
RL: 5.608

RELIABLE SURVEYS PTY LTD
 ABN 17 637 659 495
 PO BOX 226, BROOKLYN PARK SA 5032
 MOB: 0416 366 387
 EMAIL: simon@reliablesurveys.com.au

LEGEND	
	STORMWATER OUTLET
	FIRE PLUG
	FIRE PLUG MARKER POST
	IRRIGATION CONTROL VALVE
	BREATHING PIPE
	POWER TO GROUND
	SEWER MANHOLE
	SEWER INSPECTION POINT
	STOP VALVE
	SEWER ENTRY PIT
	PERMANENT SURVEY MARK
	SPRINKLER
	BACK OF KERB
	TREE TOP
	GALV. CORRUGATED IRON FENCE
	ASBESTOS FENCE
	COLORBOND/GALV FENCE
	CHAIN MESH FENCE
	POST AND WIRE FENCE
	BRUSH FENCE

NOTES:
 PLEASE NOTE ALL BOUNDARIES SHOWN HEREON HAVE BEEN DERIVED FROM DOBS DATA AND ARE APPROXIMATE ONLY. ALL DETAIL IS ON A PLANE GRID BASED ON A SINGLE MGA REFERENCE.
 SERVICES SHOWN HEREON ARE APPARENT ON THE GROUND SURFACE ONLY. QUALIFIED CABLE LOCATORS SHOULD BE ENGAGED TO CONFIRM THE UNDERGROUND POSITIONS OF ALL SERVICES INCLUDING OBSTRUCTED PITS ETC.

AMENDMENT	BY	DATE	SURVEYED BY	DATE	SCALE
			SK	26/3/20	1:200(A1)
			SK	30/3/20	FILE REF 25.20-1-R0.DWG
REFERENCE DRAWINGS	DRG. No.		SK	30/3/20	CO-ORDINATES: MGA2020
					DATUM HEIGHT DATUM: AHD
			JOB NUMBER 25.20		SHEET NUMBER 1 OF 11
					REVISION 0

**SOMERTON PARK
 OUTLET SURVEY
 HARROW ROAD OUTFALL**